

VAIO supplier facilities with certified Energy Management System



These facilities meet requirements as stated in EPEAT 1680.1 Computer & Display criterion 4.9.3.2.

| Supplier | Facility | Facility location | Certificate of Energy Management System |
|------------------------------------|---|--|--|
| Intel Corporation | Intel Ireland Ltd | Collinstown Industrial Park Leixlip Country Kildare Ireland | ISO50001 Intel Ireland.pdf |
| | Intel Chandler | 5000 W. Chandler Blvd. Chandler, AZ 85226 USA | |
| | Intel Aloha | 3585 SW 198th Ave. Aloha, OR 97007 USA | |
| | Intel Ronler Acres | 2501 NE Century Blvd. Hillsboro, OR 97124 USA | |
| | Intel Ocotillo | 4500 S. Dobson Road M/S OC2-222 Chandler, AZ 85248 USA | |
| | Intel New Mexico | 1600 Rio Rancho Blvd. S.E. M/S RR5-465 Rio Rancho, NM 87124 USA | |
| | Intel Products (Chengdu) Ltd. | No. 8-1 Kexin Road Chengdu High Tech Zone (West Park) Chengdu City Sichuan Province China 611731 | |
| | Intel Technology Sdn. Bhd. | Kulim Hi Tech Park Kulim Kedah 09090 Malaysia | |
| | Intel Technology Sdn. Bhd. | Bayan Lepas Free Industrial Zone Phase 3 Halamam Kampung Jawa Penang 11900 Malaysia | |
| | Intel Products (Vietnam) Ltd. | Lot I2, D1 Road Saigon Hi Tech Park Tang Nhon Phu Ward, Ho Chi Minh City Vietnam | |
| | Intel Electronics Ltd. | 2 Tzoran Street New Industrial Area Kiryat Gat Israel 82109 | |
| | Intel Costa Rica | Calle 129 La Ribera Belen Heredia 40701 Costa Rica | |
| Intel Santa Clara | 3065 Bowers Ave Santa Clara, CA 95054 USA | | |
| SK Hynix Inc. | SK HYNIX SEMICONDUCTOR CHINA LTD. | LOT K 7, WUXI HIGH-TECH ZONE COMPREHENSIVE BONDED ZONE IN NEW DISTRICT, WUXI, JIANGSU, 214028, P.R.CHINA | ISO50001 SK Hynix Wuxi.pdf |
| | SK hynix Inc. Icheon Campus | 2091, Gyeongchung-daero, Bubal-enb, Icheon-si, Gyeonggi-do, 17336 Republic of Korea | ISO50001 SK Hynix Icheon Cheongju.pdf |
| | SK hynix Inc. Cheongju Campus | 215, Daesin-ro, Heungdeok-gu, Cheongju-si, Chungcheongbuk-do, 28429 Republic of Korea | |
| Microsoft Corporation | Microsoft Corporation | 1 Microsoft Way, Redmond, WA, 98052-6399, USA | ISO50001 Microsoft.pdf |
| Samsung Electronics Co., Ltd. | Samsung Electronics Co., Ltd. | 1 Samsung-ro, Giheung-gu, Yongin-si, Gyeonggi-do, 17113 Republic of Korea | ISO50001 Samsung Electronics.pdf |
| | Samsung Electronics Co., Ltd. (Hwaseong Campus) | 1-2 Samsungjeonja-ro, Hwaseong-si, Gyeonggi-do, 18448 Republic of Korea | |
| | Samsung Electronics Co., Ltd. (Onyang Campus) | 158 Baebang-ro, Baebang-eup, Asan-si, Chungcheongnam-do, 31489 Republic of Korea | |
| | Samsung Electronics Co., Ltd. (Cheonan Campus) | 465 Beonyeong-ro, Seobuk-gu, Cheonan-si, Chungcheongnam-do, 31086 Republic of Korea | |
| | Samsung Electronics Co., Ltd. (Pyeongtaek Campus) | 114 Samseong-ro, Pyeongtaek-si, Gyeonggi-do, 17786 Republic of Korea | |
| Innolux Corporation | Innolux Corporation | No.168, Kesuyue Rd., Hsinchu Science Park, Miaoli County, 35053 Taiwan | ISO50001 Innolux.pdf |
| | Innolux Corporation Fab T1 (Head Quarter) | No. 160, Kesuyue Rd., Hsinchu Science Park, Miaoli County, 35053 Taiwan | |
| | Innolux Corporation Fab T2 (JOC) | No. 168, Kesuyue Rd., Hsinchu Science Park, Miaoli County, 35053 Taiwan | |
| | Innolux Corporation Fab T3 | No. 12, Kejune Rd., Hsinchu Science Park, Miaoli County, 35053 Taiwan | |
| | Innolux Corporation Fab A | No. 1, Ciye Rd., Southern Taiwan Science Park, Tainan City, 74147 Taiwan | |
| | Innolux Corporation Fab B | No. 2, Sec. 2, Huansi Rd., Southern Taiwan Science Park, Tainan City, 74144 Taiwan | |
| | Fab C/Tainan Module Fab Group II | No. 12, Nanke 8th Road, Southern Taiwan Science Park, Shanhu District, Tainan City, 74144 Taiwan | |
| | Innolux Corporation Fab D | No. 3, Sec. 1, Huansi Rd., Southern Taiwan Science Park, Tainan City, 74147 Taiwan | |
| | Innolux Corporation Tree Valley Branch (Fab E) | No. 21, Zihlian Road Building B & No. 9, Titanggang Rd., Sinshih District, Tainan City, 74148 Taiwan | |
| | Ningbo Innolux Display Ltd | No.8, Cao'e River Road, Ningbo Free Trade Zone, Zhejiang, P.R.China No.9, Yangzi River No1th Road, Comprehensive Bonded Zone, Beilun District, Ningbo City, Zhejiang, P.R.China | |
| Micron Technology, Inc | Micron Semiconductor (Xi'an) Co., Ltd | No.28-2, Xin Xi Avenue, High-tech Industries Development Zone, Xi'an, 710119 Shaanxi, P.R. China | ISO50001 Micron Technology.pdf |
| | Micron Technology Taiwan, Inc. | No.667, Fuhsing 3rd Rd., Hwa-Ya Technology Park, Taoyuan City 333, Taiwan, R.O.C. | |
| | Micron Memory Taiwan Co., Ltd. (MTB) | No. 88, Houke S. Rd. Houli Dist., Taichung City 42152 Taiwan, R.O.C. | |
| | Micron Memory Taiwan Co., Ltd. | No. 369, Sec 4, Sanfong Road, Taichung City TWN 42152 Taiwan, R.O.C. | |
| Jiangsu Transimage Technology Inc. | Jiangsu Transimage Technology Co., Ltd. | No.20,Lingbo Road,Gaoyou City,Jiangsu Province.China | ISO50001 Jiangsu Transimage Technology.pdf |
| MPT Solution Co., Ltd. | MPT Solution (Kunshan) Co., Ltd. | No. 269 (including the production workshop of K4-1 F, K7-1 F & 3F and the office area of K5-2F & K7-2F), Second Road, Kunshan Free Trade Zone and No. 168, Central Road, Kunshan Free Trade Zone-B, Jiangsu Province, P.R. China | ISO50001 MPT Solution Kunshan.pdf |
| GOOD WAY TECHNOLOGY CO., LTD. | GOOD WAY ELECTRONIC (KUNSHAN) CO., LTD. | No.101, Hengchangjing Road, Zhoushi Town, Kunshan City, Jiangsu Province, China | ISO50001 GOOD WAY ELECTRONIC KUNSHAN.pdf |
| Realtek Semiconductor Corporation | Realtek Semiconductor Corporation | No. 2, Chuangxin 2nd Rd., Baoshan Township, Hsinchu Science Park Hsinchu County, 300092 Taiwan | ISO50001 Realtek Semiconductor.pdf |